

Gapped Arresters Revisited: A Solution to Cascade Coordination

Arshad Mansoor, Member, IEEE
Power Electronics
Applications Center
Knoxville TN

François D. Martzloff, Fellow, IEEE
National Institute of
Standards and Technology *
Gaithersburg MD

Kermit O. Phipps Member, IEEE
Power Electronics
Applications Center
Knoxville TN

Abstract - This paper provides a brief perspective on how the coordination of cascaded surge-protective devices (SPDs) has become an issue. We propose an approach where the 'ancient' technology of gapped arresters may well be the answer to the dilemma of the incompatibility of a service-entrance SPD having relatively high limiting voltage with the proliferation of built-in or plug-in SPDs having relatively low limiting voltage inside the buildings. The solution involves providing a gapped arrester at the service entrance and gapless SPDs inside the building. An example is given of such a combination, with experimental verification of the proposed solution and computer modeling that allows a parametric evaluation of the significant factors in any candidate combination of SPDs.

I. INTRODUCTION

A quarter of a century ago, metal-oxide varistors ("MOVs"), initially developed as electronic components [1], [2], were introduced to power-system applications and were promptly hailed as the revolutionary technology that would make possible the elimination of gaps in surge arresters and surge-protective devices (SPDs) in general [3]. The conventional arresters at that time combined a gap with a silicon carbide (SiC) varistor disc because the I-V characteristic of silicon carbide, for the desired protection level under surge conditions, resulted in excessive standby current under the normal power system conditions.

For the high-voltage surge arresters, this SiC varistor-gap combination had reached great sophistication in the development of gap structures and construction with modular elements. For low-voltage applications, one SiC varistor disc and one gap were sufficient for the arrester function, but only a few of that type were used in residential applications. The gap sparkover characteristics made the device adequate enough for insulation protection but not effective for the protection of the emerging solid-state appliances [4]. Thus, a market was opened for all-MOV arresters to replace SiC-based gapped arresters and, as the cliché goes, the rest is history.

* Electricity Division, Electronics and Electrical Engineering Laboratory, Technology Administration, U.S. Department of Commerce.

Contributions from the National Institute and Technology are not subject to U.S. Copyright.

PE-114-PWRD-0-12-1997 A paper recommended and approved by the IEEE Surge Protective Devices Committee of the IEEE Power Engineering Society for publication in the IEEE Transactions on Power Delivery. Manuscript submitted June 9, 1997; made available for printing December 12, 1997.

However, this apparently happy state of affairs with the new, improved, MOV-based gapless SPDs is not the end of the story. Arresters developed with electric utility applications in mind were designed by specialists with strong motivation to ensure a reliable, long-life and ultimately cost-effective application of their products. This philosophy included due consideration of the maximum continuous operating voltage (MCOV), where the drive for low protection levels was tempered by the need to survive the variations and extremes of the power system environment. This criterion was well understood by utilities and manufacturers.

In this paper, we propose to show the opportunity to revive — revisit — the approach of a gapped arrester that was all but abandoned, as a possible solution to the dilemma of coordination between an arrester designed with a prudent and conservative MCOV at the service entrance, and the many SPDs proliferating inside the building and having a de facto low limiting voltage. This paper is not a product announcement but is an invitation to both manufacturers and users to recognize the opportunity and develop a viable product based on this revisited approach. We only suggest that an appropriate coordination is possible between an arrester capable of withstanding high temporary overvoltages, according to utility practice, and the small, de facto SPDs inside the building. We leave the actual product design to the ingenuity and skill of SPD manufacturers responding to the need of the utilities.

II. THE RACE FOR LOWEST PROTECTION LEVEL

Those designs are now found throughout utility systems, down to the service entrance of the end-user customers. Meanwhile, the designers of appliances, driven by the economic pressures of mass production, had selected solid-state components with relatively low surge immunity. This fateful design and marketing decision led to the need for adding surge-protective devices at the equipment level (incorporated at the power port of the appliance), or as an interface plug-in device separately purchased and installed by the end-user. There, the motivation became one of offering the lowest conceivable protection level, for instance 330 V for 120-V applications [5]. However, some of the implications of this race for the lowest protection level were not fully recognized [6].

Now, an additional concern is emerging as the idea of the so-called "whole-house surge protection" is gaining popularity. In that scheme, a relatively large SPD is installed at the service entrance and additional, smaller SPDs are installed inside the building to complement the first line of protection provided at the service entrance. The service-entrance arrester would be a simple (gapless) varistor SPD, based on the conservative

approach of the utilities (sufficient MCOV, hence medium level limiting voltage for the SPD). However the de facto situation inside the building is the uncontrolled proliferation of small SPDs with low limiting voltage. Note that given the uncoordinated status of cascaded SPDs, it would be pointless to try and pin down precisely the qualifiers of 'high', 'medium' and 'low' limiting voltage. The point is only to indicate a relative level.

This situation is uncontrolled because the design and surge immunity of appliances has not benefitted from generic standards on surge immunity. The result is that the small SPDs can in fact 'protect' the service entrance arrester and invite the largest part of an impinging surge to pass by the entrance arrester — intended to divert the large surges but by-passed — to be dissipated into the small devices — that might not be suitable for the large surge.

At this point of our discussion, we deliberately use the vague qualifier "large" to refer to the size and energy-handling capability of an SPD and to the stress threat of the impinging surge [7]. An additional concern is that inviting the flow of large surge currents inside the building has adverse side effects from the electromagnetic compatibility (EMC) point of view by shifting the potential of signal reference points associated with the equipment grounding conductors [8].

III. EMERGENCE OF COORDINATION ISSUES

These emerging issues led to the recognition of "Cascade Coordination" as an important objective for the application of SPDs. A coordinated cascade is the parallel connection of two or more SPDs across the line, one upstream and one or more downstream, each with voltage limiting characteristics that ensure sharing of the surge energy in a ratio commensurate with the energy-handling capability of each SPD.

The stage was set nearly two decades ago, with the publication of IEC Report 664 on insulation coordination [9] proposing "Installation Categories" with a descending staircase of voltages from the service entrance to the end of the branch circuits in a building. That concept was valid at the time, based on the availability of conventional arresters using a silicon-carbide varistor in series with a gap. Consequently, equipment manufacturers, including manufacturers of SPDs, became biased toward a philosophy that advocated higher limiting voltage at the service entrance and progressively lower limiting voltages inside the building.

It took some time and several contributions from independent researchers to recognize that this downward staircase cannot be implemented by a cascade of parallel-connected, varistor-type SPDs, even if separated by some distance along the wiring from the service entrance to the end of the branch circuits. This reality was first discussed in several unpublished committee working papers before a rush of published papers brought the realization into the open [10], [11], [12], [13], [14]. It turns out that SPDs included in equipment or added by users have lower limiting voltages than all-varistor SPDs installed at the service entrance and thus unintentionally "protect" the service entrance SPD by attracting the surge current to the device with the lowest limiting voltage.

IV. A POSSIBLE SOLUTION: RETURN TO A GAPPED ARRESTER


This gapped arrester will use a varistor with a limiting voltage lower than that of the downstream SPDs (in all the following text, "varistor" is to be understood as short-hand for metal-oxide varistor). The gap in series prevents steady-state application of the line voltage which the varistor cannot sustain for more than one half-cycle. An impinging surge will cause the gap to spark over, inserting the low-limiting varistor ahead of the downstream varistors. We have postulated that by appropriate selection and design of the gap, the power-frequency current which will flow in the varistor after the surge will be cleared by the gap at the first natural current zero.

4.1 Criteria for coordination

The basic principle of coordination for a cascade is that the two SPDs — for instance one upstream at the service entrance, and one downstream at the end of a branch circuit or incorporated in the connected equipment — are decoupled from each other by some impedance. With a gapped arrester at the service entrance with a varistor with limiting voltage lower than that of the downstream SPDs can serve as the most attractive SPDs in the cascade and thus divert the surge current away from internal branch circuits after the gap has sparked over. The gap can also serve to provide a higher MCOV and allow the arrester to survive the loss of neutral in a 120/240-V system.

4.2 Experimental verification

To demonstrate that it is possible to obtain a satisfactory coordination, we used our replica of a residential wiring system [8], connecting two of its branch circuits, one 4.5 m long, the other 36 m long (Figure 1). We then installed a gap-varistor combination at the service entrance of the replica and a downstream varistor either at the end of the 4.5-m branch circuit or at the end of the 36-m branch circuit. Figure 1 shows the configuration of the circuit and defines the various current and voltages that will be cited in reporting the results.



I_0 : Current delivered by the generator
 I_1 : Current flowing in gapped arrester
 I_2 : Current flowing in SPD when at ②
 I_3 : Current flowing in SPD when at ③

V_1 : Voltage at arrester
 V_2 : Voltage of SPD when at ②
 V_3 : Voltage of SPD when at ③
 V_g : voltage across gap

Figure 1 - Test circuit for experimental verification of coordination between a gapped arrester installed at the service entrance (Position ①) and an SPD installed at the end of branch circuits (Positions ② or ③)

In our replica, the power wiring uses the conventional non-metallic jacket, 2-conductor plus equipment grounding conductor (2 mm dia., AWG #12). The gapped arrester, suitable for a 120/240-V system voltage, consisted of a varistor in series with a gas tube. The downstream SPD was a typical varistor used in plug-in SPDs, rated 130 V rms [15], [16].

The surge, applied at the service entrance of the replica, was produced by a generator capable of delivering a 6 kV, 1.2/50 μ s open-circuit voltage or a 5 kA, 8/20 μ s short-circuit current, as described in IEEE C62.41-1991 [17]. Suitable \dagger differential voltage probes and current-viewing transformers were used to monitor voltages and currents during a surge event. Tests were conducted in accordance with procedures described in IEEE C62.45-1987 [18]. Instruments used for measurements are listed in the appendix, which also includes, as a contribution toward the updating of C62.45, examples of pitfalls in interpretation of digital oscilloscope recordings.


Aware of the fact that the critical point for coordination is not the maximum surge current that may be encountered in the application, but some intermediate current for which the transition occurs as the gap first sparks over, we sought that transition point for each of the line lengths considered in the experiment. We would expect that in the case of the short decoupling line, it would be more difficult to produce coordination for a given combination of downstream limiting voltage and gap sparkover, as the inductive drop would be smaller than in the case of the longer line. Nevertheless, we made both experiments because the long line, for which coordination is easier, creates other problems, as we will see later.

Figures 2, 3, and 4 show respectively, for the case of the long branch circuit, the transition from no gap sparkover to gap sparkover, occurring first on the tail of the wave, then on the front of the wave as the impinging surge current is raised.

In Figure 2, the 700-V voltage developed across the arrester is insufficient to sparkover the gap, and all the applied current (140 A peak) goes to the downstream varistor. In the experiment where the current I_0 reflects the interaction of the circuit with the generator, the current is reduced by the impedance of the long branch circuit; compared with the larger I_0 (440 A) of Figure 3 after gap sparkover. In the real world where the impinging surge is a current source, there would not be that reduction of the surge current and all of the impinging current, unimpeded, would be forced into the downstream varistor and flow in the branch circuit, an EMC problem [8].

\dagger The measurements reported in this paper have been made with instrumentation for which the combined uncertainty should not exceed $\pm 5\%$ to $\pm 6\%$. Given the process of applying the measurement results to the response of surge-protective devices exposed to environments with characteristics that are at best known within an order of magnitude, this level of uncertainty does not affect the practical conclusions.

Certain commercial instruments are identified in the appendix list of instrumentation in order to adequately describe the test procedure. Such identification does not imply recommendation or endorsement by the National Institute of Standards and Technology, nor does it imply that these instruments are necessarily the best for the purpose.




From top to bottom traces (5 μ s/div sweep):

V_1 - 200 V/div:	700 V peak
I_0 - 100 A/div:	140 A peak
I_1 - 100 A/div:	No current in arrester
I_3 - 100 A/div:	140 A peak (= I_0)

Figure 2 - Voltage and currents for a surge producing a voltage lower than gap sparkover (long branch circuit)

In Figure 3, the 750-V level developed across the arrester is sufficient to cause sparkover of the gap, but still in the tail of the wave, 4 μ s into the surge. This sparkover transfers the impinging current to the upstream arrester, limiting the rise of current into the downstream varistor at 65 A instead of 140 A.

The only stress left on the downstream varistor is to slowly discharge the energy stored in the 36-m branch circuit by the initial rise of current. Note the sudden increase in I_0 at 4 μ s as the load impedance presented to the generator changes from 36 m of cable to the short path between generator and upstream arrester.




From top to bottom traces (5 μ s/div sweep):

V_1 - 200 V/div:	750 V peak
I_0 - 200 A/div:	440 A peak
I_1 - 200 A/div:	380 A peak
I_3 - 100 A/div:	65 A peak

Figure 3 - Voltage and currents for a surge producing a voltage causing gap sparkover on the tail (long branch circuit)

With the current rise shut off in the downstream varistor as the upstream arrester starts conducting, the current in the downstream varistor is then limited to 65 A: a greater surge current results in less current in the downstream varistor after the transition of current levels from no gap sparkover to gap sparkover: "more begets less!" [19].

In Figure 4, the larger applied surge (1450 A) results in the gap sparking over on the front of the wave, with very little delay to allow only the beginning of current build-up in the downstream varistor. However, the higher voltage after sparkover (400 V, compared to 350 V in Figure 3) produces further increase in the current I_3 , an increase that does not stop until the voltage V_1 falls below 350 V, 15 μ s into the surge. This figure was recorded to show the complete event, including the end of the current pulse, and provide a comparison with Figure 2 and Figure 3 at the same sweep rate. As discussed in the Appendix, the sharp spike at the front of the voltage trace must arouse suspicions that the digital oscilloscope might have missed the peak because the need of displaying a 50 μ s window means that the resulting sampling rate, reflecting the memory size, is not sufficient to resolve the peak. The value of this figure is then limited to indicating current values and the timing of events, but not the peak of the voltage spike.




From top to bottom traces (5 μ s/div sweep):
 V_1 - 200 V/div: Not resolved - See Appendix
 I_0 - 500 A/div: 1450 A peak
 I_1 - 500 A/div: 1400 A peak
 I_3 - 100 A/div: 50 A peak

Figure 4 - Timing of sparkover and currents for a surge producing sparkover of the gap on the front of the wave (long branch circuit)

Turning now to the case of the SPD connected at the end of the short (4.5 m) branch circuit, Figure 5 shows the transition from no sparkover to sparkover. In this example, the sparkover occurs early in the tail of the wave. Instead of the spike shown in Figure 4, the occurrence of the sparkover in the tail provides sufficient data points to obtain a valid display of the voltage.

In this more difficult coordination scenario (smaller decoupling impedance afforded by the short branch circuit), the build-up of the current I_2 in the downstream varistor is greater than for the case of the long branch circuit.



From top to bottom traces (5 μ s/div sweep):
 V_1 - 200 V/div: 840 V peak
 I_0 - 500 A/div: 1010 A peak
 I_1 - 500 A/div: 780 A peak
 I_2 - 100 A/div: 230 A peak

Figure 5 - Voltage and currents for a surge causing gap sparkover into the tail (short branch circuit)

In Figure 5, the current I_2 reaches 200 A before the arrester shuts off the fast increase, about 2 μ s into the event, leaving the current with only a modest increase to 230 A before it slowly decreases, half-way into the surge event. Thus, the stress caused by the energy deposition into the downstream varistor is greater than for the case of the long branch circuit. Even so, it is still acceptable for the 20-mm diameter varistor typically used for plug-in SPDs [11]. Note also the ringing visible as the voltage V_1 reaches its maximum (840 V), resulting from the oscillation of the open-ended 36-m branch circuit.

The appearance of ringing noted in Figure 5 serves as a warning that the propagation of surges is not a simple matter [20]. To give an example of such complexity, and to give an answer to the frequently asked question "do we need an SPD on each branch circuit, or is one sufficient?" Figure 6 shows the voltage V_3 at the end of the 36-m branch circuit (Position ③, Figure 1) during a surge scenario similar to that shown in Figure 5 (one only downstream SPD located at Position ②, none in Position ③).

In the scenario of Figure 6, the long branch circuit was left open at Position ③, producing a ringing caused by reflections and undamped oscillations at that end. In this test, the driving voltage V_1 developed at the upstream gapped arrester (Position ①) is only 730 V, but the voltage at the end of the long branch circuit (Position ③) exceeds 1100 V during the ringing. Note that for an actual installation, a load connected at Position ②, where an SPD would be present in this scenario, would not be subjected to this relatively high voltage ringing. At Position ③, a load that would be connected at the end of the long branch circuit assumed to be without SPD, where the ringing occurs, is likely to damp out the ringing.

To validate this expectation, we connected a resistive load at the end of the 36-m branch circuit (Position ③), showing that the ringing can be considerably reduced, if not completely eliminated. An unloaded branch circuit, by its very definition, raises no concern for equipment since none is present.




Figure 8 - Model plot of currents, for conditions similar to Figure 4

Figure 8 shows the three current traces, similar to the current traces of Figure 4. The top trace is the applied surge, 1400 A, postulated according to Eq. (1) to match the current involved in the measurement of Figure 4. Practically the same peak values are obtained for the resulting currents, respectively 1300 A for the current in the arrester, I_1 , and 50 A for the current in the downstream SPD, I_3 . (Note that to present the three traces on the same software-driven plot, the I_3 trace is scaled by a factor of five, to fit the 500 A/div versus 100 A/div of the respective scales of Figure 4).

4.4 Other important factors

The objective of this paper, as stated in the introduction, is only to show how the dilemma of cascade coordination might be resolved by recourse to a gapped arrester at the service entrance. We have shown that effective coordination becomes possible by appropriate selection of the limiting voltages of the varistors and of the gap sparkover characteristics. However, there are other factors that will need to be addressed by designers before this approach can be transitioned to viable hardware. We have not attempted at this stage to study in detail all of these factors, but suggest the following list of topics for consideration.

These are familiar to arrester manufacturers and this list is not intended to tutor them, but simply to place the idea in perspective so that no false expectations are raised that an immediate and easy solution is already at hand. We will have accomplished our purpose if the old idea is just given new consideration. Among the topics to be studied, the following are most important:

- Ability of the varistor to reduce the follow current to a level that will allow the gap to clear at the first current zero — as postulated.
- Ability of the varistor to conduct the follow current that the power system can deliver at the point of installation.
- Ability of the gap to withstand the unavoidable power-frequency overvoltages of the power system without going into conduction and yet to have an acceptable sparkover voltage.

V. THE NEW OPPORTUNITY

The results of our experimental measurements, which can be expanded by parametric modeling, show how a happy state of affairs — an effective coordination of cascaded SPDs — could be obtained by gapped arresters at the service entrance. These arresters would combine the best of the two technologies, gas tubes and metal-oxide varistors. This will not happen, however, if the decision is not made to apply such a gapped arrester. That decision must be made by utilities and installers. In contrast, the de facto situation inside the building, imposed by millions of installed appliances, is now hopelessly immovable. Typically, when these appliances include a built-in SPD or, when the end-user purchases and installs an add-on, plug-in SPD, these SPDs are of the type with low limiting voltage [5], resulting in difficult if not impossible coordination.

This very difficult coordination, however, should not be construed as a recipe for disaster. The reality of the present situation is that these low limiting voltage SPDs manage in general to survive even in the absence of a service entrance arrester. As discussed earlier, this is not a desirable situation, hence the proposals for whole-house surge protection. But if the proposed service entrance arrester were designed to use a simple varistor with ratings commensurate with utility practices, it is most likely that the internal SPDs will “protect” the service entrance arrester, which then serves no useful purpose and is a waste of resources. Furthermore, as more electronics and equipment with low logic voltages are installed, the existing practices may lose effectiveness.

Standards or regulations cannot prescribe the particular type of service entrance arrester (furthermore, the provision of a service entrance arrester is required in only a few countries), so the decision is left to the community of utilities, SPD manufacturers and end-users. The manufacturers would probably respond to the need for gapped arresters if informed system designers were to call back from retirement the ‘ancient’ gapped device and, with appropriate technology update, give the old idea a new lease on life.

VI. CONCLUSIONS

1. The dilemma of coordinating a cascade of surge-protective devices can be solved by providing a gapped arrester at the service entrance, that will coordinate with the de facto situation inside the building.
2. The need for a service-entrance arrester to withstand the scenario of lost neutral can be satisfied by a gapped arrester having sufficient maximum continuous operating voltage capability.
3. Experimental verification of this coordination has been demonstrated for typical branch circuit lengths and limiting voltages applicable to the 120/240-V systems used in residential applications in North America. The same principles can be applied to other power systems with appropriate adaptation of voltage ratings and careful consideration of the local grounding practices.

4. The behavior of a complex system such as the interactions between circuit impedances and the nonlinear characteristics of surge-protective devices can be successfully modeled to allow parametric studies.
5. Other factors need attention, for which good engineering practice applied by surge-protective device manufacturers can provide adequate design.
6. While the idea appears sound, it cannot be implemented by individual end-users. It will take an initiative by a centralized organization, such as the utility serving the district, to persuade manufacturers that a market opportunity exists to which they can contribute.

VII. ACKNOWLEDGMENTS

Support for the development of this revisited approach was provided by the Power Quality Research groups of Delmarva Power & Light and of Pacific Gas & Electric. Support for the testing and modeling was provided by the Electric Power Research Institute.

VIII. REFERENCES

1. Matsuoka, Masyama & Ida, *Supplementary Journal of Japanese Society of Applied Physics*, Vol 39, pp 94-101, 1970
2. Harnden, Martzloff, Morris, and Golden, "Metal-oxide Varistor: a New Way to Suppress Transients," *Electronics*, October 1972.
3. Sakshaug, Kresge, and Miske, "A New Concept in Station Arrester Design," *IEEE Transactions-PES-96*, March/April 1977.
4. Martzloff, "Transient Overvoltage Protection: The Implications of New Techniques," *Proceedings, EMC Zurich 1981*.
5. UL Standard 1449, *Transient Voltage Surge Suppressors* (1980).
6. Martzloff and Leedy, "Selecting Varistor Clamping Voltage: Lower Is Not Better!" *Proceedings, EMC Zurich 1989*.
7. Key, Mansoor, and Martzloff "No Joules for Surges: Relevant and Realistic Assessment of Surge Stress Threats," *Proceedings, 7th International Conference on Harmonics and Quality of Power*, Las Vegas, September 1996.
8. Key and Martzloff, "Surging the Upside-Down House: Looking into Upsetting Reference Voltages," *Proceedings, PQA'94*, Amsterdam, October 1994.
9. IEC Publication 664, *Insulation coordination within low-voltage systems, including clearances and creepage distances for equipment*, 1980.
10. Sandler, "Coordination of Surge Arresters For Use on Low-voltage Mains," *Proceedings, EMC Zurich 1991*.
11. Lai and Martzloff, "Coordinating Cascaded Surge-protective Devices: High-Low vs. Low-High," *Conference Record, IEEE-IAS Meeting*, October 1991. Also in *IEEE Transactions, IAS 29-4 1993*.
12. Hostfet and Huse, "Coordination of Surge Protective Devices in Power Supply Systems: Needs for Protection," *Proceedings, ICLP 1992*.
13. Hasse, Wiesinger, Zahlmann and Zischank, "Principle for an Advanced Coordination of Surge Protective Devices in Low Voltage Systems," *Proceedings, ICLP 1994*.
14. Rousseau and Perche, "Coordination of Surge Arresters in the Low-Voltage Field," *Proceedings, 17th International Telecommunications Conference (INTELEC 95)*, 1995.
15. *Transient Voltage Suppression Devices*, Harris Corp., 1990.
16. IEEE C62.33-1982 (Reaffirmed 1989). *IEEE Standard Test Specifications for Varistor Surge-Protective Devices*.
17. IEEE C62.41-1991, *IEEE Recommended Practice on Surge Voltages in Low-Voltage AC Power Circuits*.
18. IEEE C62.45-1992, *IEEE Guide on Surge Testing for Equipment Connected to Low-Voltage AC Power Circuits*.
19. Mansoor and Martzloff, "Driving High Surge Currents into Long Cables: More Begets Less," *IEEE Transactions PWRD 12, No.3, July 1997*.
20. Goedde, Dugan and Rowe, "Full Scale Lightning Surge Tests of Distribution Transformers and Secondary Systems," *IEEE - PES Transmission and Distribution Conference Record*, Dallas TX, September 1991.
21. Martzloff and Gauper, "Surge and High-Frequency Propagation in Industrial Power Lines," *IEEE Transactions IA-22*, July 1986.
22. EPRI, "Electromagnetic Transients Program (EMTP), Version 2.0: Volume 1; Main Program; Volume 2: Auxiliary Routines" *EPRI Report EL-6421-L*, July 1989.
23. Martzloff, Mansoor, Phipps and Grady, "Surging the Upside-Down House: Measurements and Modeling Results," *Proceedings, PQA '95 Conference*, EPRI, 1995.



Arshad Mansoor (M' 1995) is an Electrical Systems Engineer at the EPRI Power Electronics Applications Center (PEAC). He received his MS and Ph.D. in electrical engineering from the University of Texas, Austin in 1992 and 1994 respectively. His areas of interest include Power Quality, power systems transients analysis, harmonics, surge propagation and protection, and EMTP model development.



François Martzloff (M'1956, F'1983) Born and educated in France, with additional MS degrees from Georgia Tech and Union College, worked at General Electric for 29 years and now 12 years at the National Institute of Standards and Technology. He is contributing to several committees for the development of standards on EMC, surge protection and Power Quality in the IEEE and the IEC.



Kermit Phipps is in charge of testing and evaluating equipment performance in accordance with standards of ANSI, IEEE, IEC, Military, UL, and the EPRI System Compatibility Test Protocols. At PEAC, he has conducted laboratory investigations of lamp ballasts, surge-protective devices, uninterruptible power supplies, and personal computers. He is the author of test protocols and research papers on surge propagation and power quality.