

APPENDIX A

STILL IMAGES OF THE VIDEO RECORDS USED IN CHAPTER 7

This appendix provides still images of the video records used to estimate the initial impact conditions of the aircraft that impacted World Trade Center (WTC) 1 and WTC 2 (see Chapter 7). A short description of each of these videos is provided in Table 7-1.



Figure A-1. Still image from Video V1 (WTC 1 impact).




Figure A-2. Still image from Video V2 (WTC 1 impact).



Figure A-3. Still image from Video V3 (WTC 2 impact).



Figure A-4. Still image from Video V4 (WTC 2 impact).



Figure A-5. Still image from Video V5 (WTC 2 impact).



Figure A-6. Still image from Video V6 (WTC 2 impact).



Figure A-7. Still image from Video V7 (WTC 2 impact).



Figure A-8. Still image from Video V8 (WTC 2 impact).



Figure A-9. Still image from Video V9 (WTC 2 impact).

This page left intentionally blank